

VEHICLE JOB CARD



Job No.	Job Date	Car Registration No.	Year	Mileage
AC120521	27-09-2023	DXB 62778	2017	15021
Date/Time In	Date/Time Out	Car Make	Car Model	
6.12 PM	6.13 PM	NISSAN	SENTRA	
Customer Name	Customer Contact No.	Engine No.	VIN No.	
PRAVEEN	0528449364	ENG123	VIN123456	

Reported Defect	Vehicle Body Report Comments
A/c Repair	Scratches on white body
Completed Action	
Job completed	

Technician Name	Technician Signature	Date
Basheer		27-09-2023

This is not an invoice, all estimates are valid for 30 days

Vehicle Body Report (Mark with X where damage)

